

# Best Finger Placement



identiMetrics™

Cheat Sheet

The correct finger placement is extremely important to ensure successful identifications using identiMetrics™.

## The Correct Finger Placement

1. Make sure the finger is toward the top of the scanner (no tippy toe fingers).
2. Make sure the sides of the finger are in the middle of the scanner
3. Keep the hand flat and open.



### NOTE:

Rolling fingers will not get a good scan—our system is looking for points on the finger—rolling hides those moves those points before the scanner can read them.

Need assistance? It's easy to get in touch with one of our Biometric Experts!



GO  .com



support@identimetrics.net



215-836-5640